## LinkBuilder® FDDI Workgroup Hub Module Identifier/Registration Card

Part No. 09-0460-001/May 1994

## Identifying and Inserting LinkBuilder FDDI Workgroup Hub Modules

Before you insert any modules into the LinkBuilder FDDI Workgroup Hub chassis, please fill out and return the attached Product Registration Card to ensure that your product is covered under the 3Com® Corporation warranty.



**CAUTION:** Each module is packed in an antistatic bag to protect it during shipment. To avoid damaging any highly static-sensitive components on the module or the chassis, be sure to reduce any static electricity on your person. One way to do this is to touch the metal part of the chassis. You can maintain grounding by wearing a wrist strap attached to the chassis.

Refer to the *LinkBuilder FDDI Workgroup Hub User Guide*, which is supplied with the hub chassis, for detailed module installation instructions.

The Management module (Figure 1) must be inserted in slot 0 of the LinkBuilder FDDI Workgroup Hub.



Figure 1. Management Module (Slot 0)



## **Product Registration Card**

Product#:	Quantity Purchased:	
Name		
Title		
Company		
Dept		
Telephone ()		Ext
Address		
City		
State Zip	Country	
Where did you purchase this product?		
Company		
City		
State Zip	Country	
Your company's primary network pro	tocol? (select one)	
DOSI DDLC	□SNA	□NBP
□ TCP/IP □ DECnet	□XNS	□ Other
a rei/ii		
Your company's primary network ope		
	3 Com 3+Open LAN Manage	
	DEC	□ PC NFS
□ Other		
What applications are used on your ne	twork? (check all that apply)	
☐ Desktop publishing ☐ Spread	dsheet	ing CAD/CAM
☐ Database management ☐ Accord	unting	☐ Other
What category below best describes yo	ur company? (select one)	
Non-computer-Related		Computer-Related
☐ Retail/Distribution/Wholesale	☐ Healthcare/Medical	□ Consulting
☐ Transportation/Utilities/Communicati	on Legal	□Distributor
☐ Engineering/Architecture/R&D	□ Education	□ VAD/VAR (Independent)
☐ Finance/Banking/Accounting	☐ Aerospace	☐ VAD - Franchise or Outlet
☐ State & Local Government	■ Manufacturing	☐ Software Developer
☐ Federal Government, inc. military ☐ Other	☐ Insurance/Real Estate	☐ Hardware Developer ☐ Other
Would you be interested in joining a 30	Com Hear's Group?	
Yes No	om oser s Group:	
□ 1cs □ IN0		

II.d.,d.d.ll.,a.d.d.,d.d.,d.d.,dl.,dl.d.

The Fiber port module (Figure 2) can be inserted in slots 1, 2, or 3. Do not leave any slot empty between modules.



Figure 2. Fiber Port Module (Slot 1, 2, or 3)

The UTP port module (Figure 3) can be inserted in slots 1, 2, or 3. Do not leave any slot empty between modules.



Figure 3. UTP Port Module (Slot 1, 2, or 3)

The STP port module (Figure 4) can be inserted in slots 1, 2, or 3. Do not leave any slot empty between modules.



Figure 4. STP Port Module (Slot 1, 2, or 3)

The Fiber/UTP media module (Figure 5) can be inserted in slots 1, 2, or 3. Do not leave any slot empty between modules.



Figure 5. Fiber/UTP Media Module (Slot 1, 2, or 3)



3Com Corporation 5400 Bayfront Plaza P.O. Box 58145 Santa Clara, California 95052-8145 © 1994, 3Com Corporation. Printed in the U.S.A.

POSTAGE WILL BE PAID BY ADDRESSEE FIRST CLASS MAIL INES SS REPL
PERMIT NO. 1883

3Com Corporation P.O. Box 58145 SANTA CLARA, CA 95052-9953

SANTA CLARA, CA

NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

Untitled-1 2 4/4/97, 12:26 PM